



WATER PUMPS FOR KOMATSU®

CTP offers a wide array of replacement water pumps for Komatsu® engines. Water pumps generally do not require any maintenance, they are a simple in design and should last the life of the engine. However, when a water pump begins to weep excessively, this is a sign that the water seal is failing. Losing coolant in an engine can lead to a catastrophic and costly engine failure.

Part No.	Application
6124-61-1004	S4D155, S6D155
6127-61-1008	S6D155, SA6D155
6131-62-1205	S4D105
6136-61-1102	6D105, S6D105
6136-61-1601	6D105
6136-62-1100	S6D105
6138-61-1860	S6D110, SA6D110
6150-61-1105	6D125
6151-62-1104	6D125E, S6D125E, SA6D125E, SAA6D125E
6154-61-1102	SA6D125E, SAA6D125E
6162-63-1016	S6D170, S6D170E, SA6D170, SA6D170E, SAA6D170E
6204-61-1104	S4D95 4D95L Engine PC60-5 PC75UU-2 PC120-5
6204-61-1304	4D95S
6205-61-1202	4D95LE, PC118MR, PC88MR, PW118MR, S4D95LE, SAA4D95LE, SAA4D95LE_5A, WA150PZ
6206-61-1104	4D95L, 4D95LE, 6D95L, S4D95L, S6D95L, SA6D95L
6206-61-1505	6D95L, S6D95L
6209-61-1100	PC200, PC210, PC220, PC250, S6D95L, SA6D95L, SAA6D95LE
6211-62-1403	S6D140, S6D140E, SAA6D140E
6212-61-1205	S6D140, SA6D140, SA6D140E, SAA6D140E, SDA6D140E
6212-61-1305	S6D140E, SA6D140, SA6D140E, SAA6D140E
6221-61-1102	PC300-5 D57S-1B PC310-5 Engine 6D108
6222-61-1500	S6D108
6222-63-1500	SAA6D108E
6240-61-1102	SA6D170E, SAA6D170E
6251-61-1101	HM300, PC400, PC450, SAA6D125E, WA470, WA480
6685-61-1024	NH, NTC, NTO
6731-62-1120	SAA6D102E, WA320, WB142, WB146, WB146PS, WB156, WB156PS
6742-01-5578	850B, 870B, D61EX, D61PX, GD650A, PC300, S6D114E, WA320, WA380, WA420
6743-61-1531	6D114 PC300-7 PC350-7 PC360-7 WA380-5
6754-61-1010	SAA6D107E PC200-8

* Other part no. not included in the list are available. Please contact your sales representative if you have any questions. Part Numbers are used for reference purposes only. Komatsu® is the registered trademark of Komatsu Ltd.